

Residential Pre-Purchase Building Inspection Report

Complies with Australian Standard AS 4349.1-2007 Inspection of Buildings Part 1: Pre-Purchase Inspections Residential Buildings - Appendix C



Client: Deborah Wood Property Address: 7/20 Herbert Street Dulwich Hill Date of inspection: 14/06/2016



1 of 24

The Property Inspectors

Ph: +61 2 9181 5989 Mob: 0411 880 588 Address: 80 Victoria Rd Drummoyne NSW 2047

admin@thepropertyinspectors.com.au

Mail: PO Box 290 Hunters Hill NSW 2110

DISCLAIMER OF LIABILITY TO ANY THIRD PARTIES:

IMPORTANT

The information on this page is important and must be read before looking at the accompanying report.

You should not rely on this report if you wish to purchase the property.

This Report has been prepared for the Client, as listed on the cover page of this report, and for the exclusive use of the Client only.

Accordingly you should not rely upon this document if you intend to purchase the property to which it relates.

In receiving or viewing this report you are acknowledging that you will not rely upon it if you intend to purchase the property. If you require information contained in this report you should seek out and commission the completion of your own report. In that regard, The Property Inspectors can supply a report that you can rely upon. Please see our website: www.thepropertyinspectors.com.au if you wish to purchase such a report. Alternatively, you can arrange for another contractor to provide you with a report.

The Property Inspectors will not accept any responsibility and shall not be liable for any loss or damage, including in negligence, arising out of or in connection with any use or eliance on the statements, comments, photographs or any other information in this report.

This report does not take into account your individual needs of the property. Consideration of your individual needs of the concerns can affect the recommendations and conclusions of the author of the report. Even if you are in possession of this report, or have knowledge of its contents or are aware of the author, as you have not purchased it you have no entitlement to discuss the report or your individual needs of concerns with the author.

You, as reader, must accept sole resporsibility for what you do in relation to any material contained in the report. If you do not agree, do not read this report. You can purchase a report that you can rely upon via our website or by contacting The Property Inspectors.



2 of 24

The Property Inspectors

Mob: 0411 880 588 Ph: +61 2 9181 5989 Address: 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110

admin@thepropertyinspectors.com.au

Contents	Pari
Purpose and Scope of Inspection	1
General comments and weather conditions	2
Description of Building	3
Areas Inspected	3a
Interior	4
Exterior	5
Roof Exterior	6
Roof Space	7
Sub Floor Space	8
Roof Space Sub Floor Space The Site Restrictions of access Defects and Safety issues	9
Restrictions of access	10
Defects and Safety issues	11
Other Inspections & Reports Required	12
Cracking to Building Members	13
Conclusion & Summary	14



3 of 24

The Property Inspectors

Mob: 0411 880 588 Address: 80 Victoria Rd Drummoyne NSW 2047 admin@thepropertyinspectors.com.au Ph: +61 2 9181 5989 Mail: PO Box 290 Hunters Hill NSW 2110 www.ThePropertyInspectors.com.au

Results of Inspection - Summary

A Summary of the inspection is below:

	Found	Not Found
Safety Hazard		✓
Major Defect		✓
Minor Defect	\checkmark	

Please refer to the report for explanations.

The overall condition of this residential Dwelling in the context of its age, type and general expectations of similar properties is Above Average.





4 of 24

The Property Inspectors

Mob: 0411 880 588 Address: 80 Victoria Rd Drummoyne NSW 2047 admin@thepropertyinspectors.com.au Ph: +61 2 9181 5989 Mail: PO Box 290 Hunters Hill NSW 2110 www.ThePropertyInspectors.com.au

Part 1: Purpose and Scope of Inspection

This report complies with Australian Standard AS4349.1 - 2007 Inspection of Buildings, Part 1: Pre Purchase Inspections - Residential Buildings.

Inspection Agreement - Individual title property

Requirement for Inspection agreement AS 4349.1 - 2007 requires that an inspection agreement be entered into between the inspector & the client prior to the conduct of the inspection. This agreement sets out specific limitations on the scope of the inspection and on limits that apply in carrying it out. Where specific State or Territory requirements apply in addition to the scope of work in this agreement, or where the inspector and client agree to additional matters being covered, that additional scope is listed at the end of this agreement. It is assumed that the existing use of the building will continue.

Purpose of Inspection

The purpose of the inspection is to provide advice to a prospective purchaser or other interested party regarding the condition of the property on the date and at the time of the inspection. The advice is limited to the reporting of the condition of the Building Elements in accord with Appendix B or C AS4349.1-2007 (Appendix B for Strata or Company Title and Appendix C for other residential buildings).

Important Information and Disclaimer

Any person who relies upon the contents of this report does so acknowledging that the following clauses both below **and** at the end of this report. These define the Scope and Limitations of the inspection and form an integral part of the report. Before you decide to purchase this plope by you should read and understand all of the information contained herein. It will help explain what is in plyed in a Pre-Purchase Building Inspection Report, the difficulties faced by an inspector and why it is not possible to guarantee that a property is free of defects, latent or otherwise. This information forms an integral part of the report. If there is anything contained within this report that is not clear or you have difficulty understanding, please contact the inspector prior to acting on this report.

The extent and thoroughness of bir inspection has been limited by our reading of what was reasonable by way of time, intrusion and risk of doing relysical damage to the property being inspected. We have not inspected woodwork or other parts or the structure which are covered, unexposed or inaccessible and we are therefore unable to report that any such part of the structure is free from defect. Identification of hazardous materials or situations that may be in the building or on or near the property is outside the scope of this inspection. This report is not a certificate of compliance of the property within the requirements of any Act, regulation, ordinance, local law or by-law, and is not a warranty against problems developing with the building in the future. This report does not include the identification of unauthorised building work or of work not compliant with building regulations. With respect to minor defects, the inspection is limited to reporting on their overall extent. It is not intended to detail each and every individual minor defect or imperfection. This service is provided on an independent professional basis. It seeks to present a factual, unbiased and balanced assessment. We have no financial interest in any work that may be recommended or in any share of commission if the property is sold.



5 of 24

The Property Inspectors

Mob: 0411 880 588 Ph: +61 2 9181 5989 <u>Address</u>: 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110

admin@thepropertyinspectors.com.au

Scope of Inspection

The inspection comprised a visual assessment of the property to identify major defects and safety hazards, and to form an opinion regarding the general condition of the property at the time of inspection. An estimate of the cost of rectification of defects is outside the scope of the Standard and therefore does not form part of this report.

AS 4349.1 - 2007 requires that the basis for comparison is a building of similar age and similar type to the subject building and which is in reasonable condition, having been adequately maintained over the life of the building. This means that building being inspected may not comply with Australian Standards, building regulations or specific state or territory requirements applicable at the time of the inspection.

What is reported on:

- The inspection includes subjective appraisal by an inspector competent to assess the condition of residential buildings. It involves a subjective assessment so different inspectors or even the same inspector on a different occasion may reach different conclusions
- The inspection comprises a visual assessment of the property to identify major defects and to form an opinion regarding the general condition of the property at the time of inspection.
- The following areas shall be inspected where applicable:
 - The interior of the building: ceilings; walls; floors; windows; doors & frames; kitchen;
 bathroom; WC; ensuite; laundry; stairs & damp problems
 - The exterior of the building: walls (including lintels, claddings, doors & windows); timber or steel frames & structures; chimneys; stairs; balconies, verandas, patios, decks, suspended concrete floors, balustrades
 - The roof exterior: roof (including tiles, shing as that is, roof sheeting, gables, flashings); skylights, vents, flues; valleys, cuttoring, downpipes; eaves, fascias and barges
 - The roof space: roof covering; roof frathing; parking; party walls; insulation
 - The sub-floor space: timber floor (including supports, floor, ventilation, drainage, damp); suspended concrete foor
 - The property within 5m c. the yous, and within the boundaries of the site: car accommodation, detained boundary, ablution facilities and garden sheds; retaining walls (where supposing other structures and landscaping retaining walls > 700mm high); paths & driveways; steps; for icing (excluding swimming pool fences); surface water (drainage effectiveness)

What is not reported on:

- general exclusions detailed in the standard AS 4349.1 2007
- Parts of a building that are under construction
- The inspection is not intended to include rigorous assessment of all building elements in a property
- Defects that would only be apparent under particular weather conditions or when using particular fittings & fixtures
- · Defects not apparent due to occupancy or occupancy behavior eg non use of a leaking shower



6 of 24

The Property Inspectors

Mob: 0411 880 588 Ph: +61 2 9181 5989 <u>Address:</u> 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110

admin@thepropertyinspectors.com.au

- · The inspection report is not a certificate of compliance of the property within the requirements of any Act, regulation, ordinance, local law or by-law and is not a warranty against problems developing with the building in the future
- · Unauthorized building work or of work not compliant with building regulations
- · Title and ownership matters, matters concerning easements, covenants, restrictions, zoning certificates and all other law-related matters
- · Estimation of the cost of rectification of specific defects.
- Specifics excluded by the standard AS 4349.1 2007 Footings below ground, concealed dampproof course, electrical installations, operation of smoke detectors, light switches and fittings, TV, sound and communication and security systems, concealed plumbing, adequacy of roof drainage as installed, gas fittings and fixtures, air conditioning, automatic garage door mechanisms, swimming pools and associated filtration and similar equipment, the operation of fireplaces and solid fuel heaters, including chimneys and flues, alarm systems, intercom systems, soft floor coverings, electrical appliances including dishwashers, incinerators, ovens, ducted vacuum systems, paint coatings except external protective coatings, health hazards e.g., allergies, soil toxicity, lead content, radon, presence of asbestos or urea formaldehyde), timber and metal framing sizes and adequacy, concealed tie downs and bracing, timber pest activity, other mechanical or electrical equipment (such as gates, inclinators), soil conditions, control joints, sustainable development provisions, concealed framing-timbers or any areas concealed by wall linings or sidings, landscaping, rubbish, floor cover, furniture and accessories, stored items, insulation, environmental matters e.g. BASIX, water tanks, BCA environmental provisions, energy efficiency, lighting efficiency.

Special Requirements

It is acknowledged that there are no special requirements placed thi inspection that are outside the scope of the abovementioned Australian Standard.

Limitations

This report is limited to a visual inspection of are as where safe and reasonable access is available and access permitted on the date access the condition of the property at the date and time of inspection. Areas for Inspection shall cover all safe and accessible areas. It does not purport to e geological as to foundation integrity or soil conditions, engineering as to structural, nor does it cover the condition of electrical, plumbing, gas or motorised appliances. It is strongly recommended that an appropriately qualified contractor check these services prior to purchase.

As a matter of course, and in the interests of safety, all prospective purchasers should have an electrical report carried out by a suitably qualified contractor & a structural engineer carry out an assessment of the structural integrity of the property.

This report is limited to (unless otherwise noted) the main structure on the site and no other building, structure or outbuilding within 5m of the main structure and within the site boundaries including fences.



7 of 24

The Property Inspectors

0411 880 588 Address: 80 Victoria Rd Drummoyne NSW 2047 admin@thepropertyinspectors.com.au www.ThePropertyInspectors.com.au

Ph: +61 2 9181 5989 Mail: PO Box 290 Hunters Hill NSW 2110

Safe and Reasonable Access

Only areas to which safe and reasonable access is available were inspected. The Australian Standard 4349.1 defines reasonable access as "areas where safe, unobstructed access is provided and the minimum clearances specified below are available, or where these clearances are not available, areas within the inspector's unobstructed line of sight and within arm's length. Reasonable access does not include removing screws and bolts to access covers." Reasonable access does not include the use of destructive or invasive inspection methods nor does it include cutting or making access traps or moving heavy furniture, floor coverings or stored goods.

Dimensions for Reasonable Access

Roof Interior - Access opening = 400 x 500 mm - Crawl Space = 600 x 600mm - Height accessible from a 3.6m ladder.

Roof Exterior - Must be accessible from a 3.6m ladder placed on the ground.





admin@thepropertyinspectors.com.au

8 of 24

The Property Inspectors

Mob: 0411 880 588 Ph: +61 2 9181 5989 Address: 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110

Part 2: General Comments and Weather Observations

Weather Conditions at the time of inspection

Recent weather conditions

Date and time inspection completed

Building furnished?

Occupied by?

Report prepared for?

Clear & Sunny

Clear & Sunny

14 June 2016 9:47 PM

Yes

Owner

Buyer

Part 3: Description of Building

Style of Building

Number of Stories

Age of Building (approx)

Roof Covering

Roof frame

Roof Pitch (Approximate, in degrees)

External walls

Floor Construction

Footings

Outbuildings

Front of Building Faces (approx)?

Conventional Low Set

Three Storey

30-50 years old

Concrete Tiles

Timber Hand Pitched

25

Bare Masonry Block

Timber on imber Frame, Composite Sheet on

Timber I al e. Faft Concrete Slab

Concrete Strip Footing, Brick Piers on Concrete

pad, Sto on Ground

Not Applicable

South



9 of 24

Ph: +61 2 9181 5989

The Property Inspectors

Mob: 0411 880 588

admin@thepropertyinspectors.com.au

Address: 80 Victoria Rd Drummoyne NSW 2047

Mail: PO Box 290 Hunters Hill NSW 2110

General Photographs:

Part 3a: Areas Inspected

The Actual Areas Inspected were:

Interior of Building

Part 4: Interior of Building

Ceilings; Are all ceilings free of sagging, nail popping, cracking, staining or other damage?

Minor sagging in places

Some sagging of the plasterboard ceiling is evident in places.

Location: Living room

Details: Crazed cracks in ceiling lining

Defect Rating: Minor Defect



Walls; Are the wall linings free of bulging, nail popping, cracking, dampness/staining, vertical distortion and other damage?

Imperfections in flush jointing

Imperfections in flush jointing - The imperfections could easily be rectified prior to the next painting.



10 of 24

The Property Inspectors

Mob: 0411 880 588 Ph: +61 2 9181 5989 Address: 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110

admin@thepropertyinspectors.com.au

Location: Generally the walls are in good condition with a few minor imperfections within the wall linings which is typical for an apartment of this age

Defect Rating: Minor Defect

Floors (Timber); Are floors free of movement such as spring and bounce, and cracking, and are they free of dampness/staining and other damage?

Minor spring & bounce

The flooring has minor spring and bounce, which is typical of a building of this age.

Defect Rating: Minor Defect

Windows (Metal framed); Are all windows free of broken/cracked glass, damage to glazing seals, staining/corrosion, or do they operate freely?


Yes

Doors/Frames; Do all doors and hardware operate freely and do not bind on frames, and are they free of decay/corrosion and other damage?

Minor maintenance required

Location: Bedroom door handle needs attention

Defect Rating: Minor Defect







11 of 24

The Property Inspectors

Mob: 0411 880 588 Ph: +61 2 9181 5989 Address: 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110

admin@thepropertyinspectors.com.au

Kitchen; Is the benchtop free of lifting,

delamination, water damage or other damage?

Kitchen; Are the cupboards free of water damage,

musty odour?

Kitchen; Do the cupboard doors and drawers
Drawers swollen and binding

operate freely?

Location: A number of doors bind and require adjustment

Defect Rating: Minor Defect





Yes

Yes

Kitchen; Are the sinks/taps free of chips, cracks and/or water leaks?

Kitchen; When water supply is stritched or does it **Yes** operate and drain correctly?

Kitchen; Are the tiles free of cracking, drumminess, **Yes** or loose/missing grout/sealant?

Bathrooms/WC; Are cisterns/pans/bidets Free of cracks, leakages, or do they flush correctly?

Bathrooms/WC; Are cisterns/pans/bidets correctly **Yes** installed and are they stable/rigid?

Bathrooms/WC; Are taps free of leaks, and does Yes

the water supply operate correctly?



12 of 24

The Property Inspectors

Mob: 0411 880 588 Ph: +61 2 9181 5989 Address: 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110

admin@thepropertyinspectors.com.au

Bathrooms/WC; Are the tiles free of cracks, drumminess, or loose/missing grout/sealant?

Cracked tiles

Location: Cracked wall tiles

Missing grout Excess sealant

Defect Rating: Minor Defect





Bathrooms/WC; Is the bath free of damage, and is it properly recessed at the junction with the wall?

Ye.

Bathrooms/WC; Is the shower screen free of cracks, and is it adequately sealed at the floor/w junctions?

Yes

Bathrooms/WC; Are the shower cracking, drumminess, or loose/missing grout/sealant?

Yes

Bathrooms/WC; Around the shower, is it free of signs of leaking/seepage?

Doors/drawers bind on cabinet frame

Bathrooms/WC; Is the vanity basin, cabinet and mirrors free of damage, and do the doors/drawers operate correctly?

Defect Rating: Minor Defect



13 of 24

The Property Inspectors

Mob: 0411 880 588 Address: 80 Victoria Rd Drummoyne NSW 2047 admin@thepropertyinspectors.com.au Ph: +61 2 9181 5989 Mail: PO Box 290 Hunters Hill NSW 2110 www.ThePropertyInspectors.com.au



Bathrooms/WC; Is the room free of condensation damage, and is it adequately ventilated?

Yes

Laundry; Are taps free of leaks, and does the water supply operate correctly?

Yes

Laundry; Are the tiles free of cracks, drumminess, or loose/missing grout/sealant?

Other

Location: Inconsistent grout colour used in wall tiles Samp

Defect Rating: Minor Defect



14 of 24

The Property Inspectors

Mob: 0411 880 588

Ph: +61 2 9181 5989 Address: 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110

admin@thepropertyinspectors.com.au www.ThePropertyInspectors.com.au



Laundry; Is the room free of condensation damage, and is it adequately ventilated?

Yes

Electrical; Do all powerpoints, switches and fittings

Yes

appear to be cosmetically undamaged?

Yes

Electrical; Do all light fittings appear to be cosmetically undamaged?

Yes

Electrical; Does the mains power board (and the submain if applicable) have circuit breakers and a

safety switch?

Yes. A RCD safety switch was installed, however, it have commended an electrician carry out a safety inspection as I am not able to ascertain if an electrical defects exist or any non-compliant electrical works have been carried out at this direction prior to purchasing this dwelling.

Electrical; Do battery or hardwire exist?

Yes

Yes. Smoke alarms have been installed. Smoke alarms should be checked and tested by a licensed electrician prior to occupancy of this dwelling.

All rooms: Are all rooms free of damp problems, including rising/falling damp, condensation,

Yes

horizontal penetrating dampness?

All rooms; Are all rooms free of any other damage or defects?

Yes



15 of 24

The Property Inspectors

Mob: 0411 880 588 Ph: +61 2 9181 5989 Address: 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110 admin@thepropertyinspectors.com.au

Part 5: Exterior of Building

Stairs; Are the stringers, handrails, balusters, treads and risers sufficiently rigid and free of damage?

Balconies/verandahs/patios/decks/suspended floors/balustrades; Do they appear structurally sound, free of defects?

Balconies/verandahs/patios/decks/suspended floors/balustrades; Are handrails at correct height to comply with Building Code?

General; Is the exterior free of any other damage or defects?

Yes

Yes

Appear to be in reasonable condition for their age

Yes

Yes

Part 6: Roof Exterior

Part 7: Roof Space

Part 8: Sub Floor Space

Part 9: The Site

Samp

Part 10: Restrictions

Did the inspector have unrestricted access to all areas?

Areas not inspected including reasons were:

Yes

Sub floor **Roof void** External elements of the property All common property and body corporate property



16 of 24

The Property Inspectors

Ph: +61 2 9181 5989 Mob: 0411 880 588 Mail: PO Box 290 Hunters Hill NSW 2110 Address: 80 Victoria Rd Drummoyne NSW 2047 admin@thepropertyinspectors.com.au

Areas to which access should be gained, or fully gained, are:

Roof Void; No access door, Sub Floor: No access door

Roof Void: No access door installed., Sub Floor: No access door installed.





17 of 24

The Property Inspectors

Mob: 0411 880 588 Ph: +61 2 9181 5989 Address: 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110

admin@thepropertyinspectors.com.au

Part 11: Summary of Defects and Safety Issues

Safety Hazards in this Building:

No Safety Hazards Identified

Major Defects in this Building:

No Major Defects Identified

Minor and Other Defects in this Building:

Ceilings; Are all ceilings free of sagging, nail popping, cracking, staining or other damage?

Minor sagging in places

Some sagging of the plasterboard ceiling is evident in places.

Location: Living room

Details: Crazed cracks in ceiling lining

Defect Rating: Minor Defect

Walls; Are the wall linings free of bulging, nail popping, cracking, dampness/staining, vertical distortion and other damage?

Impen ct. ons in flush jointing

Imperfections in flush jointing - The imperfections could easily be rectified prior to the next painting.

Location: Generally the wall arguing decondition with a few minor imperfections within the wall linings which is typical for an apartment of this age

Defect Rating: Minor Defect

Floors (Timber); Are floors free of movement such as spring and bounce, and cracking, and are they free of dampness/staining and other damage?

Minor spring & bounce

The flooring has minor spring and bounce, which is typical of a building of this age.

Defect Rating: Minor Defect



18 of 24

The Property Inspectors

Mob: 0411 880 588 Ph: +61 2 9181 5989 Address: 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110

admin@thepropertyinspectors.com.au

Doors/Frames; Do all doors and hardware operate freely and do not bind on frames, and are they free of decay/corrosion and other damage?

Minor maintenance required

Location: Bedroom door handle needs attention

Defect Rating: Minor Defect

Kitchen; Do the cupboard doors and drawers

enerate freely?

Drawers swollen and binding

operate freely?

Location: A number of doors bind and require adjustment

Defect Rating: Minor Defect

Bathrooms/WC; Are the tiles free of cracks, drumminess, or loose/missing grout/sealant?

Cracked tiles

Location: Cracked wall tiles

Missing grout Excess sealant

Defect Rating: Minor Defect

Bathrooms/WC; Is the vanity basin, cabinet and mirrors free of damage, and do the doors/drawers operate correctly?

Ders/a awars bind on cabinet frame

Defect Rating: Minor Defect

Laundry; Are the tiles free of cracks, dry hminess, or loose/missing grout/sealant?

Other

Location: Inconsistent grout colour used in wall tiles

Defect Rating: Minor Defect



19 of 24

Ph: +61 2 9181 5989

The Property Inspectors

Mob: 0411 880 588
Address: 80 Victoria Rd Drummoyne NSW 2047
admin@thepropertyinspectors.com.au

Part 12: Other Inspections & Reports Required

Recommendations for Further Inspections:

Sub floor area Pest inspections Roof void

Part 13: Cracking to Building Members

Is there cracking to the Building Members: No

If cracks have been identified in the table below, then A Structural Engineer is required to determine the significance of the cracking prior to a decision to purchase.

Regardless of the appearance of the cracks a Pre Purchase Building Inspector carrying out a Pre Purchase Inspection within the scope of a visual inspection is unable to determine the expected consequences of the cracks.

Obtaining information regarding:

- (a) The nature of the foundation material on which the building is resting,
- (b) The design of the footings,
- (c) The site landscape,
- (d) The history of the cracks and
- (e) Carrying out an invasive inspection,

all fall outside the scope of this Pre Purchase Inspection. It is ever the information obtained from the five items above are valuable, in determining the expected consequences of the cracking and any remedial work needed.

Cracks that are small in width at a length of the day of the inspection may have the potential to develop over time into Structural Problems for the Hor e Owner resulting in major expensive rectification work been carried out.

Areas Inspected	Location	Description of the Cracking Defect at the time of the Inspection.
Concrete Slabs		
Suspended Concrete Slabs		



20 of 24

The Property Inspectors

Mob: 0411 880 588 Ph: +61 2 9181 5989 Address: 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110

admin@thepropertyinspectors.com.au

Masonary Walls	
Piers	
Retaining Walls	
Other Areas	

IMPORTANT: All Recommendations made in the above Inspection Findings or elsewhere in this Report should be carried out/or considered in your decision process, prior to purchase.





21 of 24

The Property Inspectors

Mob: 0411 880 588
Address: 80 Victoria Rd Drummoyne NSW 2047
admin@thepropertyinspectors.com.au

Ph: +61 2 9181 5989 Mail: PO Box 290 Hunters Hill NSW 2110

Part 14: Conclusion & Summary

The purpose of the inspection is to identify the major defects and safety hazards associated with the property at the time of the inspection. The inspection and reporting is limited to a visual assessment of the Building Members in accord with Appendix C AS4349.1-2007.

The overall condition of this building has been compared to similar constructed buildings of approximately the same age where those buildings have had a maintenance program implemented to ensure that the building members are still fit for purpose.

The incidence of Major Defects in this Residential Building as compared with similar Buildings is considered:

None

The incidence of Minor Defects in this Residential Building as compared with similar Buildings is considered:

Low

The overall condition of this residential Dwelling in the context of its age, type and general expectations of similar properties is:

Above Average

Overall Condition Comments:

Overall, the apartment is in very good ond ion for its age

The apartment has no stry ctural tailure

The apartment has very little cos netic defects that need to be addressed

Overall this property is a well built, well maintained and well renovated apartment

Please Note: This is a general appraisal only and cannot be relied on its own - read the report in its entirety.

This Summary is supplied to allow a quick and superficial overview of the inspection results. This Summary is NOT the Report and cannot be relied upon on its own. This Summary must be read in conjunction with the full report and not in isolation from the report. If there should happen to be any



22 of 24

The Property Inspectors

Mob: 0411 880 588 Ph: +61 2 9181 5989 Address: 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110

admin@thepropertyinspectors.com.au

discrepancy between anything in this Report and anything in this summary, the information in the report shall override that in this summary.

We take this opportunity to thank you for your instructions and we look forward to working with you again.

Emilio Calandra

The Property Inspectors





23 of 24

The Property Inspectors

Mob: 0411 880 588 Ph: +61 2 9181 5989 Address: 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110

www.ThePropertyInspectors.com.au

admin@thepropertyinspectors.com.au

Definitions

High: The frequency and/or magnitude of defects are beyond the inspector's expectations when compared to similar buildings of approximately the same age that have been reasonably well maintained.

Typical: The frequency and/or magnitude of defects are consistent with the inspector's expectations when compared to similar buildings of approximately the same age that have been reasonably well maintained.

Low: The frequency and/or magnitude of defects are lower than the inspector's expectations when compared to similar buildings of approximately the same age that have been reasonably well maintained.

Above Average: The overall condition is above that consistent with dwellings of approximately the same age and construction. Most items and areas are well maintained and show a reasonable standard of workmanship when compared with buildings of similar age and construction.

Average: The overall condition is consistent with dwellings of approximately the same age and construction. There will be areas or items requiring some repair or maintenance.

Below Average: The Building and its parts show some significant defects and/or poor non-tradesman like workmanship and/or long term neglect and/or defects requiring major repairs or reconstruction of major building elements.

Major Defect: Is a Defect requiring building works to avoid unsafe conditions, loss of function or further worsening of the defective item.

Minor Defect: Any Defect other than what is decorbed s major defect.

Accessible area: is any area of the property and structures allowing the inspector safe and reasonable access within the scope of the inspection.



24 of 24

The Property Inspectors

Mob: 0411 880 588 Ph: +61 2 9181 5989 <u>Address</u>: 80 Victoria Rd Drummoyne NSW 2047 Mail: PO Box 290 Hunters Hill NSW 2110

admin@thepropertyinspectors.com.au